

展开尺寸 : 660x240mm 折后尺寸 : 55x120mm, 材质 : 105g 铜板 , 正反面四色印刷

#### Laser Distance Meter 102253 Series Quick Start

##### Product Overview

The product is a handheld laser distance meter. It is designed to measure distances quickly before using.

102253 is perfect assistant to satisfy measuring needs of straight and curved lines.

Portable size, simple design and easy to use.

Easy readings with large LCD screen.

Supports direct measurement and back.

Built-in lithium rechargeable battery.

By integrating laser measuring with wheel measuring, 102253 has solved a variety of problems. It can measure from straight to curve lines, it widely used in construction, decoration, checking and inspection etc.

##### Safety Instructions

For the safe use of this handheld laser distance meter, please read below instructions carefully.

**① Warning**

MAINTAIN DRY AND DUST FREE

a. This product is a class I laser product so please don't look directly at the laser beam or aim the laser beam at others when using it. It is safe to your eyes.

b. This product complies with general standards and regulations, but it does not guarantee that it will not interfere that products will interfere with other equipment and may have an adverse effect on other equipment.

c. Please do not use this product near medical equipment. Do not use this product near explosive materials.

d. Waste disposal.

Protecting the environment is our responsibility.

Used batteries are not allowed to be disposed of in domestic waste. Please dispose used batteries at designated garbage collection station.

The product is not allowed to be disposed of with domestic waste. Please dispose of the product according to regional implementation laws and regulations.

e. Scope of liability:

If the instrument is not used in accordance with the instruction, damage caused due to user's own fault will not be covered by manufacturer's responsibilities.

**Lithium Battery Charging Instructions**

This product has a built-in lithium battery. Please use the original USB cable while charging, you also can charge by

connecting to a computer, but it takes about 1 hour.

▲ Laser distance meter may heat up when charging, it is normal, has no effect on the device performance and service life. It is not recommended to charge the charger for too long time, under the charger

Appearance

1. Laser on  
2. Reference foran/bak  
3. Power button  
4. LCD display  
5. Memory  
6. Current data

##### Functional Operation Instructions

ON/OFF

Long press to power ON/OFF. Short press to change the measuring units.

##### Single Measurement

The device will enter Single measurement when it is powered ON, press after aiming at target to get result at bottom of the screen.

##### Continuous Measurement

Long press to activate Continuous measurement, aim at the target and press to stop, the current data will be displayed.

\*The continuous measurement will stop automatically after 5 minutes.

MIN MAX

##### Wheel Measurement

Short press to activate wheel measurement.

3.ON/CFF/ Unit change

Long press to turn ON/CFF.

4. Wheel Measure button

5. Strap

6. Micro USB interface

7. Wheel

LCD Display

1. Display  
2. Measure Button   
Short press to single measurement  
Long press to start wheel measurement

3.ON/CFF/ Unit change

Short press to switch m/f/in/mm

4. Wheel Measure button

5. Strap

6. Micro USB interface

7. Wheel

LCD Display

1. Display  
2. Målepunkt  
Kort tryk på for enkeltmåling. Langt tryk på målepunkten for å bytte mellom m/f/in/mm.

3.AV/PÅ/ Bytte måleenhett

Kort trykke på for å bytte mellom m/f/in/mm.

4.Hjulmåling

Trykk kort på for å åpne hjul.

Hjulmålingen blir aktivert fra startskjut.

Trykk kort på igjen for å slå hjulmålinga.

Måleverdien vises på displayet.

5.Hull for stroop

6.Mikro-USB-kontakt

7.Hjul

LCD display

1. Display

2.Målepunkt

Kort trykks for enkeltmåling. Langt trykks for hjulmåling.

3.AV/PÅ/ Bytte måleenhett

Kort trykks for å bytte mellom m/f/in/mm.

4.Hjulmåling

Trykk kort på for å åpne hjul.

Hjulmålingen blir aktivert fra startskjut.

Trykk kort på igjen for å slå hjulmålinga.

Måleverdien vises på displayet.

5.Hull for stroop

6.Mikro-USB-kontakt

7.Hjul

LCD display

1. Display

2.Målepunkt

Kort trykks for enkeltmåling. Langt trykks for hjulmåling.

3.AV/PÅ/ Bytte måleenhett

Kort trykks for å bytte mellom m/f/in/mm.

4.Hjulmåling

Trykk kort på for å åpne hjul.

Hjulmålingen blir aktivert fra startskjut.

Trykk kort på igjen for å slå hjulmålinga.

Måleverdien vises på displayet.

5.Hull for stroop

6.Mikro-USB-kontakt

7.Hjul

LCD display

1. Display

2.Målepunkt

Kort trykks for enkeltmåling. Langt trykks for hjulmåling.

3.AV/PÅ/ Bytte måleenhett

Kort trykks for å bytte mellom m/f/in/mm.

4.Hjulmåling

Trykk kort på for å åpne hjul.

Hjulmålingen blir aktivert fra startskjut.

Trykk kort på igjen for å slå hjulmålinga.

Måleverdien vises på displayet.

5.Hull for stroop

6.Mikro-USB-kontakt

7.Hjul

LCD display

1. Display

2.Målepunkt

Kort trykks for enkeltmåling. Langt trykks for hjulmåling.

3.AV/PÅ/ Bytte måleenhett

Kort trykks for å bytte mellom m/f/in/mm.

4.Hjulmåling

Trykk kort på for å åpne hjul.

Hjulmålingen blir aktivert fra startskjut.

Trykk kort på igjen for å slå hjulmålinga.

Måleverdien vises på displayet.

5.Hull for stroop

6.Mikro-USB-kontakt

7.Hjul

LCD display

1. Display

2.Målepunkt

Kort trykks for enkeltmåling. Langt trykks for hjulmåling.

3.AV/PÅ/ Bytte måleenhett

Kort trykks for å bytte mellom m/f/in/mm.

4.Hjulmåling

Trykk kort på for å åpne hjul.

Hjulmålingen blir aktivert fra startskjut.

Trykk kort på igjen for å slå hjulmålinga.

Måleverdien vises på displayet.

5.Hull for stroop

6.Mikro-USB-kontakt

7.Hjul

LCD display

1. Display

2.Målepunkt

Kort trykks for enkeltmåling. Langt trykks for hjulmåling.

3.AV/PÅ/ Bytte måleenhett

Kort trykks for å bytte mellom m/f/in/mm.

4.Hjulmåling

Trykk kort på for å åpne hjul.

Hjulmålingen blir aktivert fra startskjut.

Trykk kort på igjen for å slå hjulmålinga.

Måleverdien vises på displayet.

5.Hull for stroop

6.Mikro-USB-kontakt

7.Hjul

LCD display

1. Display

2.Målepunkt

Kort trykks for enkeltmåling. Langt trykks for hjulmåling.

3.AV/PÅ/ Bytte måleenhett

Kort trykks for å bytte mellom m/f/in/mm.

4.Hjulmåling

Trykk kort på for å åpne hjul.

Hjulmålingen blir aktivert fra startskjut.

Trykk kort på igjen for å slå hjulmålinga.

Måleverdien vises på displayet.

5.Hull for stroop

6.Mikro-USB-kontakt