



**DT-1630**

**HAND HELD & POCKET DIGITAL THERMOMETER**

Our most popular, practical and user-friendly model. With **"HI-LOW"** programmable alarm function. With °C or °F selection, battery and probe.

**FEATURES**

- Temperature range: **-50°C to +300°C (-58°F to +572°F)**.
- Read out in Celsius (°C) or Fahrenheit (°F).
- Soft cable with probe: **100 cm** long.
- Stainless steel probe: **10 cm** long (with tip protector).
- Retractable desk stand.
- Resolution: **0,1°C (0,1°F)**.
- Accuracy: **± 1°C from -20°C to +60°C**  
**± 5°C** all other ranges
- Alarm sounds when temperature reaches **"HIGH"** or **"LOW"** values as pre-selected.
- Battery AAA (1,5 V) included.
- Dimensions: **59 mm x 107 mm x 20 mm (W x H x D)**.
- 6 months warranty.



**DTH-1628**

**HAND HELD & POCKET DUAL DIGITAL THERMO-HYGROMETER (°C & °F)**

Displays indoor and outdoor temperatures and indoor relative humidity simultaneously.

**FEATURES**

- Temperature measuring range (unit: indoor sensor) **0°C to +50°C (+32°F to +122°F)**.  
Temperature measuring range (probe: outdoor sensor) **-50°C to +70°C (-58°F to +158°F)**.
- Operation temperature: **0°C to +50°C (+32° to +122°F)**.
- Relative humidity: **25 % to 95 % at +25°C (+77°F)**.
- Temperature display resolution indoor sensor: **1°C (2°F)**.
- Temperature display resolution outdoor sensor: **0,1°C (0,1°F)**
- Resolution of humidity: **1 % (Relative Humidity)**.
- Temperature sampling cycle: **10 seconds**.
- Humidity sampling cycle: **10 seconds**.
- Selection of Celsius (°C) or Fahrenheit (°F) by slide switch.
- Relative humidity measurement is temperature-compensated.
- **"WET"** Indicator: **Over 65 %** of Relative Humidity.
- **"DRY"** Indicator: **Below 45 %** of Relative Humidity.
- Wall mounting feature.
- 2 batteries AA (1,5 V) included.
- Battery life: **± 1 year**.
- Dimensions: **82 mm x 154 mm x 20,5 mm (W x H x D)**.
- 6 months warranty.



**SP-120**

**SOLAR POCKET POWER THERMOMETER**

Switchable in Celsius (°C) or Fahrenheit (°F)

**FEATURES**

- Operates by using ambient light sources.
- Back up battery AAA (1,5 V DC) included.
- Measuring range: **-50°C to +70°C (-58°F to +158°F)**.
- Resolution: **0,1°C**.
- Accuracy: **± 1,5°C (± 3°F)**.
- Ambient temperature: **-18°C to +48°C (0°F to +120°F)**.
- **47,5 mm x 15,8 mm** LCD display.
- Remote sensor length: **3 meter (120")**.
- 6 months warranty.